

MARYLAND GEOLOGICAL SURVEY  
Merryman Hall  
The Johns Hopkins University  
Baltimore, Maryland 21218  
(301) 235-0771

COUNTIES (MD/PA) CECIL/CHESTER

M&D milestone no. 9 (10)

MHT-HSI no. CE-IX-1017

PROTECTED/ENDANGERED/MISSING

FIELD SHEET: MASON & DIXON LINE, MARYLAND-PENNSYLVANIA BOUNDARY MARKER SURVEY

LOCATION: USGS 7.5' quadrangle Bay View UTM 18.41770.439711  
original site/moved/date 1766 redetermined & stone reset bench mark/date none observed  
1900-03 Resurvey (site now obliterated; stone missing)

Site: about 0.7 mile NW of Lombard; about 600' due E of Weaver house on E/S of unmarked road leading to Chrome, PA, in cultivated field about 400' S of deciduous woods.

DIRECTIONS TO SITE:

From M&D 8 (9): follow Barren Road SW about 1.3 miles to junction of unmarked road to Chrome, PA; turn right (NW) & follow 0.3 mile to State line & Weaver house; park on road R/W, clear access to site with owner.

DESCRIPTION/MEASUREMENTS: original/replica/replacement/date 1766 (now missing);  
Foundation not found

N face (PA):

E face:

S face (MD):

W face:

top:

bench mark: none indicated on maps; none observed

CONDITION OF MARKER/FOUNDATION: excellent/good/fair/deteriorated/ruins/missing & unexposed  
1900-03 Resurvey notes (order no. 10), as in MGS Vol. 7, 1908, p. 83

10. Milestone No. 9, M.&D., 1766, in field east of road leading from Lombard, Md., to Chrome, Pa. The position of this monument had been lost. It was redetermined and the stone was then reset.

1950 Inspection notes (present order no. 9, photo no. 9) as in Bayliff, 1959, Appendix C, p. 95

10. Top broken off and lost. Base completely buried in cultivated field.

1979-80 Inspection notes: order no. 9 (10); photos/negatives/slides 9 (10)

9 (10) Original M&D milestone of 1766 not at site & foundation not found. Survey point & foundation endangered by farming.

SURROUNDING PROPERTY OWNERS (MD/PA): names, addresses, phones

MD: tax map 5, block , P. 17, deed RRC 9/56, ac. 102.6, index  
Harmon J. Weaver, RD 1, Nottingham, PA 19362

PA: tax map 70, block 3, P. 37, deed /, ac., index  
Harmon J. & Jewel Weaver, RD 1, Nottingham, PA 19362

RECORDED BY: names, addresses, phones, dates Jean Ewing 4/2/80, 5/10/80  
P.O. Box 66, Darlington, MD 21034 (301) 457-4757

Assisted by Miss Frances Taylor  
Conowingo, MD 21918

Also see: reverse side X, B&W photos X, negatives X, color slides X, maps X,  
MHT-HSI form, other

## NOTES

This milestone was missing and the foundation(site) obliterated. We were not able to find anyone who could locate the foundation in the field or who knew where the stone might be housed.

RECOMMENDATIONS: We suggest that official contact be made with the <sup>and others</sup> owner/in an effort to establish both/site <sup>foundation</sup> and the stone whereabouts. Eventually, the original or replacement should be reset and marked with witness post.

## B&W PHOTOS/NEGATIVES

5x7 View ENE (neg # 16A) Stephanie Yatsevitch 5/19/80

## COLOR SLIDES

View ENE (8) Jean Ewing 5/80

## MAPS


USGS 7½' topographic quadrangle section  
1900-03 Resurvey engineer's map (Plate VIII), updated  
MD tax map section

## OTHER

5763 - SE  
(KIRKWOOD)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

BAY VIEW QUADRANGLE  
MARYLAND - PENNSYLVANIA  
USGS 7.5 MINUTE SERIES (TOPOGRAPHIC)  
1953 PHOTO REV. 1970  
SCALE: 1" = 2000' 57'30"







Mason & Dixon pass. bis: mi. stral<sup>th</sup> 7 site.

Site only, approximate location on y. of stral removed  
looking ENE from blower yard.

Photo: Stephanie Yatskevitch 19 May 80 (Reg # 4a)